


530 PBM



Operating instructions

350-8196-000 a1



Declaration of conformity

**Declaration of conformity for apparatus with CE mark
Konformitätserklärung für Geräte mit CE-Zeichen
Déclaration de conformité pour appareils portant la
marque CE Declaración de conformidad para aparatos
con disitintivo CE**

Dichiarazione di cofnromità per apparecchi contrassegnati con la marcatura CE

- English** We hereby declare that the product to which this declaration refers conforms with the following standards.
- German** We hereby declare that the product to which this declaration refers complies with the standards below.
- Français** Nous déclarons avec cela responsabilité que le produit, auquel se rapporte la présente déclaration, est conforme aux normes citées ci-après.
- Español** Manifestamos en la presente que el producto al que se refiere esta declaración est´a de acuerdo con las normas siguientes
- Italiano** Dichiariamo con ciò che il prodotto al quale la presente dichia-razione si riferisce è conforme alle norme di seguito citate.

**Moisture Balance: Precisa PBM 60
 Precisa PBM 60 HR
 Precisa PBM 66**

with infrared radiator, halogen radiator or dark radiator

Mark applied	EU Directive	Standards
	2014/30/EU 2014/35/EU	EN61326 EN61010-1:2010

Date: 08.05.2024

Signature:



R. Grolimund R&D Manager

Precisa Gravimetrics AG, Moosmattstrasse 32,
P.O. Box 352, CH-8953 Dietikon

Identification

This instruction manual applies to the Precisa 530 Series PBM moisture analyzers with ten-button control panel and multifunction display.

Customer service

Precisa Gravimetrics AG
Moosmattstrasse 32
CH-8953 Dietikon
Tel. +41-44-744 28 28
Fax. +41-44-744 28 38
email service@precisa.ch

<http://www.precisa.com>


Information and addresses of local customer service points can be found on our website.

Copyright

This instruction manual is protected by copyright. All rights reserved. No part of the operating instructions may be reproduced, processed, duplicated or distributed in any form by photocopying, microfilm, reprint or other processes, in particular electronic methods, without the written permission of Precisa Gravimetrics AG .

© Precisa Gravimetrics AG, 8953 Dietikon, Switzerland, 2024.

Overview







No.	Description	Paragraph
1	Heaters (halogen/IR/dark radiator heaters)	6.1
2	Temperature sensor PT1000	0
3	Sample dish	3.3/ 6.2
4	Sample dish Holder	3.3
5	Weighing pan	3.3
6	Draftshield	3.3
7	Level	3.7
8	10 key membrane keypad	5.1
9	Display	
10	Adjustable feet	3.7
11	Fan	4
12	Mains fuse, T 3.15 A, 230 V; T 6.3 A, 115 V	9.2
13	Mains connection socket	3.5
14	Ethernet port, optional	5.3.11
15	USB host port for connecting keyboard, barcode reader, ...	5.3.11
16	Serial port port, DB9 female	5.3.11
17	USB device socket for connection to a PC	5.3.11
18	Level	
19	ON/OFF button	4
20	Menu Button	5.3.1/ 5.4.1
21	Tare Button	5.5.1
22	Heating Mode Button	6.3.1
23	Temperature button	6.3.2
24	Time Button	6.3.3
25	Stop Mode Button	6.3.4
26	Start/Stop button	5.5.4
27	Change button	5.5.3
28	Print Button	5.5.2
29	Unit Display	5.3.25
30	Display	4
31	Weighing aid	5.3.24
32	Heating mode display (info line)	4
33	Temperature display (info line)	4
34	Drying time display (info line)	4

Firmware and serial number

After reconnecting the moisture analyzer to the mains and switching it on for the first time, the serial number and firmware are displayed after the short initialization sequence.

Display	Remark
<i>Miscellaneous information</i>	Start-up sequence
	All display elements of the screen must light up
	Serial Number: 9101422
	Firmware: H00-0000. P02 H00: Hardware Code 00.00: Version P02: Release
PBM 60	Model

Accessories

Accessories

	Article
Printer LP4024, 230V / 115V	350-8391
Bluetooth connection for printer LP4024	350-8391-001
Paper roll LP4024, set of 4 pieces	350-8392
Adhesive paper roll LP4024, set of 5 pieces	350-8396
Ribbon for printer LP4024	PN 3953-013
Adapter RJ45-DB9f, (PC/Printer LP4024)	350-8522
Data cable DB9m-DB9f, 1.5m, (PC/Printer LP 4024, 1:1)	350-8672
USB cable A-B, 1.5m, (PC)	PN 3950-125
Interface box, LAN Ethernet connection	350-8940-001
Interface box, WiFi connection	350-8940-002
Interface box, Bluetooth connection	On request
Anti-theft, mechanical	350-8555
Dust cover for display (20 pieces)	350-8590
Aluminum trays with collar (box of 80 pieces)	350-1015
Stainless Steel Sample Tray, Reusable (1 Piece)	330-2018
Fiberglass filters (80 pieces)	350-4130
Temperature Sensor Plate (Sensor - Type K)	350-8580
Temperature calibration set (sensor - type K), with certificate	350-8585
Temperature calibration set (sensor - type K), without certificate	350-8584
Dust filter complete	350-8587
Adjustment weight 50 g	350-8241

Content

Identification	1
Customer service	1
Copyright	1
Overview	2
Firmware and serial number	7
Accessories	8
1 Introduction	11
1.1 Useful information about the operating instructions	12
1.2 Warranty	12
2 Safety	9
2.1 Representations and Symbols	9
2.2 Safety	9
3 Commissioning	11
3.1 Unwrap	11
3.2 Transport, storage	12
3.3 Scope of delivery and installation	13
3.4 Selection of the appropriate location	14
3.5 Creating a power connection	15
3.6 Protective measures	16
3.7 Leveling	16
3.8 Weight Calibration	17
4 First measurement	18
5 Service	21

5.1	Principle of operation of the menu control	21
5.2	Setting and Saving the Configuration	24
5.3	Device	24
5.5	Specially operated buttons	49
6	Moisture determination	47
6.1	Basics	47
6.2	Sample	48
6.3	Setting Drying Parameters	50
6.4	Statistics (PBM 60, PBM 60-HR)	56
7	Ash residue program	58
7.1	Ignition residue determination for PBM 60 and PBM 60-HR	59
7.2	Ash residue PBM 66	60
8	Data transfer	64
8.1	Connection Scheme	65
8.2	Remote Control Commands	66
9	Service	68
9.1	Maintenance and care	68
9.2	Replacing the mains fuse	69
9.3	Calibration, adjustment	70
	Internal Calibration	72
	Automatic internal calibration.....	73
9.4	Firmware update	76
9.5	Error	76
10	Overview	77
10.1	Specifications	77
10.2	Menu Overview	79

1 Introduction

The moisture analyzer is easy and functional to use. It is used for fast and reliable determination of material moisture in liquid, porous and solid materials using the thermogravimetry method.

The moisture analyzer impresses with:

- Easy and quick cleaning
- High-end weighing technology according to the highest international standards
- Optimal resolution
- Large, bright display (LCD)
- LED status indicator (ready/cold or operating/cooling)
- Memory for 30 methods (PBM 60, PBM 60-HR), with all drying settings
- Automatic endpoint detection (as per setting)
- Securing the device configuration and drying parameters against unauthorized modification by password
- Anti-theft code
- Printout according to GLP guidelines (Good Laboratory Practice)
- Software update via Internet
- High-resolution version PBM 60-HR with 10 times higher readability for weight and individual units of humidity calculation. For details, please refer to chapter 5.3.25 "Units".

■ 1 Introduction

1.1 Useful information about the operating instructions

Read these operating instructions completely and carefully so that you can make the most of the full potential and the many possibilities of the device in your daily work.

This instruction manual contains orientation aids in the form of pictograms and button representations, which should make it easier for you to find the information you are looking for:

- Key names are enclosed in quotation marks and highlighted in bold letters: "**ON/OFF**" or "**⏻**".
- When explaining the operating steps, the corresponding display is graphically displayed to the left of the list of operating steps:

Display



Key



Step

Press repeatedly until the currently enabled language is displayed.

1.2 Warranty

The instruction manual is accompanied by a warranty card, which was completed by your Precisa representative before handing over the moisture analyzer.



NOTE

Check that the warranty card is included in this instruction manual and that it is filled out.



2 Safety

2.1 Representations and Symbols

Important instructions relating to safety are highlighted in the respective job description:

 DANGER
Warning of a possible hazard that could lead to death or serious bodily injury.

 WARNING
Warning of a potentially dangerous situation that may result in minor bodily injury or property damage.

 NOTE
Tips and important rules for working correctly with the moisture analyzer.

2.2 Safety

- If the device is used in environments with increased safety requirements, the relevant regulations must be observed.
- Only use extension cords with a protective conductor.
- If the power cord is damaged, the device must be immediately unplugged and the power cord replaced.
- If, for any reason, it can be assumed that it is no longer possible to operate the moisture analyzer safely, it must be immediately disconnected from the power supply and secured against unintentional operation.
- When carrying out maintenance work, it is essential to comply with the requirements set out in Chapter 9.1 "Maintenance and Care" become.

■ 2 Security

- The operating instructions must be read by each operator of the equipment and must be available at the workplace at all times.

DANGER

Do not place flammable materials on, under or next to the device.

Keep enough space around the appliance to prevent heat build-up.

Potentially explosive, highly flammable samples must not be analyzed with the moisture analyzer.

Do not operate the moisture analyzer in potentially explosive atmospheres.

Sample materials that release toxic substances must be dried under a special suction device. It must be ensured that no harmful fumes can be inhaled.

Make sure that no liquid gets inside the device or into ports on the back of the device.

If liquid is spilled on the device, it must be immediately unplugged.

The moisture analyzer must not be operated again until it has been checked by a Precisa service technician.

WARNING

Individual parts can heat up heavily during operation. Touch the device only by the handles provided for this purpose.

Be careful when taking the sample. The sample itself, the heating unit and the sample trays used can still be very hot.

The moisture analyzer should be used primarily for drying water-containing substances. Sample materials that emit aggressive fumes (e.g. acids) can lead to corrosion problems on equipment parts.

In the event of damage, liability and responsibility lie with the user.

3 Commissioning

3.1 Unwrap

The moisture analyzer is supplied in an environmentally friendly packaging specially developed for this precision instrument, which optimally protects the device during transport.



NOTE

Keep the original packaging to avoid damage during shipment or transport of the moisture analyzer and to be able to store the device optimally in the event of a longer period of decommissioning.

To avoid damage, the following points must be observed when unpacking the moisture analyzer:

- Unpack the device with calm and care. It is a precision instrument.
- At very low outside temperatures, the appliance should first be stored for a few hours in the unopened transport packaging in a dry, normally temperature-controlled room so that no condensation moisture settles on the appliance during unpacking .
- Immediately after unpacking, check the moisture analyzer for any externally visible damage. If you notice any transport damage, please inform your Precisa service representative immediately.
- If the moisture analyzer is not to be used immediately after purchase, but will only be put into operation at a later date, it should be stored in a dry place with as little temperature variation as possible (see chapter 3.2.2 "Storage").
- Read this instruction manual, even if you have previous experience with Precisa equipment, before using the device. and observe the safety instructions (see chapter 2 "Safety").

■ 3 Commissioning

3.2 Transport, storage

3.2.1 Transport & Shipping

Your moisture analyzer is a precision device. Treat it with care. Avoid shocks or vibrations during transport.

Make sure that there are no strong temperature fluctuations during transport and that the device cannot become damp (condensation).



NOTE

It is preferable to ship and transport the moisture analyzer in its original packaging to avoid damage during transport.

3.2.2 Storage

If you want to take the device out of service for a longer period of time, disconnect it from the mains, clean it thoroughly (see chapter 9 "Service") and store it in a place that meets the following conditions:

- No strong shocks, no vibrations
- No major temperature fluctuations
- No direct sunlight
- No moisture




NOTE

It is preferable to store the moisture analyzer in its original packaging, as this provides optimal protection for the device.

3.3 Scope of delivery and installation

The moisture analyzer is delivered in a partially disassembled state. Immediately after unpacking all the parts, check whether the delivery is complete and assemble the individual components in the order given below.



Delivery Components	Delivery Components
Moisture analyzer	Sample Holder (3)
Power cord	20 Sample Trays (4)
Draft shield (1)	5 Fiberglass Filters
Weighing pan (2)	Operating instructions

■ 3 Commissioning

- Open the hood and insert the draft shield (1), making sure that it lies flat
- Insert the weighing pan (2) and rotate it so that the anti-twist device clicks into place
- Insert the sample holder (3) as shown
- Now you can place an aluminium tray (4) on the weighing pan



NOTE

All parts must be able to be put together without effort. Do not use force. If you have any problems, Precisa customer service will be happy to help you.

3.4 Selection of the appropriate location


To ensure proper functioning of the moisture analyzer, the location must be chosen in such a way that the following conditions are met:

- Permissible environmental conditions
 - Temperature: 10°C ... 35°C (storage and transport 0 ... 50 °C)
 - Relative humidity: 15% - 85%, (at T to 30 °C)
non-condensing, linearly decreasing up to 50% at 50 °C
 - Max. permissible altitude: ≤ 4000 m
- Place the device on a rigid, firm horizontal surface, exposed to as little vibration as possible.
- Protect the device against shaking and falling
- No direct sunlight and no dusty environment
- No draughts and no excessive temperature fluctuations
- Sufficient free space in the vicinity of the device to prevent heat build-up

Do not expose the device to high humidity for long periods of time. Avoid condensing humidity on the instrument. First, disconnect very cold appliances from the mains at room temperature (approx. 20°C).

When the device is connected to the mains, condensation is practically impossible.

3.5 Creating a power connection



When connecting the device to the mains, the following safety instructions must be observed:



DANGER

The device may only be operated with the original power cord supplied.

If the length of the supplied power cord is insufficient, only use an extension cable with a protective conductor.

Connect the power cord to a properly installed socket with a protective conductor (PE) connection.

For technical reasons, the heating unit is designed for a voltage value of 230 V or 115 V at the factory and is matched accordingly to your order. Does the setting match the local mains voltage?

3.6 Protective measures


The moisture analyzer of protection class 1 may only be connected to a socket with a protective conductor connection (PE) that has been installed in accordance with the regulations. The protective effect must not be cancelled out by an extension line without a protective conductor. In the case of powersupply from networks without a protective conductor connection, equivalent protection must be provided by a specialist in accordance with the applicable installation regulations.

3.7 Leveling


To function properly, the moisture analyzer must be positioned exactly horizontally.

The device is equipped with a "bubble level" for level control and four rotatable feet, which can be used to compensate for minor differences in height or unevenness of the equipment base.

The feet must be adjusted so that the air bubble in the bubble level is exactly in the center of the round glass marking.



False



Correct



NOTE

To obtain accurate readings, the device must be carefully re-leveled after each change of location.

3.8 Weight Calibration

Since the value of the gravitational acceleration is not the same at every place on earth, each device must be adapted to the gravitational acceleration prevailing there at the installation site - in accordance with the underlying physical weighing principle. This adjustment process, called "calibration", must be carried out at the first start-up and after each change of location. In order to obtain accurate readings, it is also advisable to calibrate the moisture analyzer periodically.



NOTE

The moisture analyzer must be calibrated at the first start-up and after each change of location.

If you work according to "Good Laboratory Practice GLP", observe the prescribed intervals for calibration (adjustment).

The calibration can be set in the configuration menu (see chapter 5.3.6 "Balance Calibration").



■ 4 First measurement

4 First measurement


After the successful commissioning of the moisture analyzer, we carry out an initial measurement to familiarize ourselves with the new device and test it for any malfunctions.

Turn on the device with the "**ON/OFF**" button. The device performs a self-diagnosis to check the most important functions. At the end of the start-up process (which takes about ten seconds), the display will show "zero", i.e. the device is now ready for use.

During the first measurement, the device works with the drying parameters set at the factory.

	<p>Open the hood (press up on the blue handle)</p> <p>Place the sample holder with an empty sample tray on the sample tray holder.</p> <p>Note that the sample tray lies flat on the sample tray holder.</p> <p>Always work with the sample holder, it allows safe working and prevents burns.</p>
	<p>Press the "T" button</p>
	<p>The device is ready for weighing the sample.</p> <p>Add approx. 1.0 g of water to the sample tray.</p>

4 First measurement

	<p>Close the hood.</p> <p>The device is prepared for the first measurement.</p>
	<p>Start the measurement with the «START/STOP» button.</p>


The heating element heats up to 105 °C and the fan begins to cool.

■ 4 First measurement

+	100.00 %
STD	19 °C 0.1MIN

+	93.27 %
STD	105°C 2.3MIN

+	XX.XX %
---	---------



The display of the moisture analyzer is divided into:

the display of measured values and the info line

- In the measured value display, the result appears in the set unit.
- The info line shows the heating mode used (standard), the current temperature (105°C) and the current duration of the measurement (2.3 minutes).
- When drying is finished, an acoustic signal sounds and the heating is switched off.
- The measured value display shows the result in the set unit. By pressing the «» button, the measurement result is displayed in the other units.
- The info line shows the duration of the measurement.
- Open hood
- Carefully remove the sample tray, grasping the handle of the sample holder only.
- Be careful, all parts of the sample chamber are hot.
- Allow the sample tray and holder to cool down before continuing work.

4 First measurement

- Insert a new sample tray into the instrument
- Press the "T" button, the device is prepared for a new measurement.



WARNING

The sample tray and the sample holder are hot!

5 Service

The moisture analyzer has two main menus: the configuration menu and the application menu.

In the **configuration menu**, device-specific parameters and the design of the drying protocol are defined. You can either work with the basic configuration programmed at the factory or define and save a user configuration adapted to your specific needs.

Dryer-specific parameters can be set in the **application menu**. In addition, the weighing aid is activated and defined in this menu.

5.1 Principle of operation of the menu control

The configuration menu and the application menu each have a main path and up to two secondary paths, in which the parameters for the various functions of the device are defined.

Use the cursor keys « », « », « » and « » to move within the paths.

■ 5 Operation



NOTE

The geometry of the menu tree diagram corresponds to the path assignments of the two main menus.

When navigating the **Menu** (chapter 5.1 "Principle of operation of the menu control") the menu functions apply (bottom button symbols) on the double-occupied control button.

From the measurement mode, the upper application functions (large button symbols) apply.

Button(s)	Designation	Function from measurement mode
	« », «⇒»	<ul style="list-style-type: none"> • Switch from the main menu path to the side paths and back
 	«↑» «↓»	<ul style="list-style-type: none"> • Move up/down within the main or secondary paths. • Changing selected parameters
	«⇐»	<ul style="list-style-type: none"> • Selecting parameters • Saving the modified parameters
	«esc»	<ul style="list-style-type: none"> • Aborting an input • Leaving the menu
	«ins»	<ul style="list-style-type: none"> • Set insertion point (for text input)
	«clr»	<ul style="list-style-type: none"> • Deleting Input (for Text Input)



	«PRINT»	<ul style="list-style-type: none">• Entering a decimal point (for text input)
---	---------	---

The device can also be operated remotely. Among the relevant For remote control commands, see chapter 8.2 "Remote Control Commands".

5.2 Setting and Saving the Configuration

See chapter 5.3.18 " Set Configuration ".

5.3 Device

This section explains the structure of the configuration menu and its functions.

Main Path	definable functions
SET DATA PRINT	<i>Print formats; Define the type of values to be printed</i>
SET APP. MENU	<i>Define application menu</i>
SET GLOW.	<i>Define ignition residue determination (PBM 66 only)</i>
SET BALNCE CAL.	<i>Define balance calibration mode</i>
TEMP. ADJUST-MENT	<i>Activate temperature adjustment</i>
STABILITY	<i>Define the quality of the weighing location</i>
QUICK-START	<i>Enable QUICK-START</i>
REFILL	<i>Activate solvent addition option</i>
SET RS 232	<i>Define baud rate, parity, handshake functions of the peripheral interface</i>
SET USB DEVICE	<i>Define the operating mode for the USB device connection</i>
SET USB HOST	<i>Define the operating mode for the USB host connection</i>
SET DATE AND TIME	<i>Date and time (standard format or American format p.m. and a.m.)</i>
PASSWORD	<i>Password protection for the menu definitions</i>
THEFT CODE	<i>Activation/deactivation and modification of the anti-theft code</i>
KEYNOTE	<i>Enable/set keyboard sound</i>
ALERT TONE	<i>Activate/set notification sound</i>
BACKLIGHTING	<i>Adjust screen brightness</i>
LANGUAGE	<i>Language (E, D, F, T, S)</i>
SET CONFIGURATION	<i>Load/save configuration</i>

Display conventions:

- The factory-programmed settings are in **bold**
- For a better overview, only the part of the menu tree that corresponds to this function is displayed for each function description.
- Explanations of the menu functions are printed in *italics*.

5.3.1 Activating the Configuration Menu

- Press "**ON/OFF**" to turn on the device.
- During the start-up process, press and hold the "**MENU**" button until the "SET DATA PRINT" indicator appears.
- Now you can change the settings in the configuration menu.

5.3.2 Language Function

• LANGUAGE		
LANGUAGE GERMAN		<i>Select language</i>
LANGUAGE ENGLISH		
LANGUE FRANCAISE		
DIL TURKEY		
IDIOMA ESPANOL		

To change the language, follow these steps:

Display	Key	Step
LANGUAGE ENGLISH	«↓»	<i>Press repeatedly until the current enabled language is displayed.</i>
LANGUAGE ENGLISH	« »	<i>The language flashes and can be changed.</i>
LANGUAGE GERMAN	« »	<i>Press repeatedly until the desired language is displayed.</i>
LANGUAGE GERMAN	«↵»	<i>Input confirm.</i>

You can exit the menu by pressing the "**esc**" key.

5.3.3 Configuring Log Expression

In the menu item "SET DATA PRINT" the drying protocol can be configured. The items marked "ON" are included in the protocol and are printed.

With the "MODE PC" function, the measured value printout can be output in a format that is convenient for the PC. This format only has an influence on the print rate printout and is used for the graphical evaluation of the drying process with the help of a PC program (e.g. Excel). The individual measured values are output separately by a tab and can therefore be easily imported into a table.

• SET. DATA PRINT			
	SET PRINT FORMAT	DATE AND TIME	ON/OFF
		BALANCE ID	ON/OFF
		METHOD ID	ON/OFF
		NUMERATOR	ON/OFF
		DRYER SETUP	ON/OFF
		PRINT RATE	ON/OFF
		OPERATOR ID	ON/OFF
		CAL.-INFO	ON/OFF
		PRINT RATE	1.0 MIN
		OPERATOR	ttt...
SET HEADLINES	TITLE 1	ON/OFF	
	TITLE 2	ON/OFF	
	TITLE 1	ttt...	
	TITLE 2	ttt...	
MODE	PRINTER	<i>Printout in text format (40 characters)</i>	
	PC	<i>Print rate printout in PC-compatible format. The individual measured values are separated by a tab</i>	

The elements set to "SET PRINT FORMAT" are printed.

- With "PRINTRATE" the interval in which the intermediate results are printed is set. The print interval is from 0.1 ... 10.0 min adjustable in 0.1 min increments.
- In the case of "OPERATOR ttt..." , the operator can be entered alphanumerically.

When connecting a peripheral device (e.g. a printer), the device interface must be selected in the submenu "SET RS 232" (see chapter 5.3.11 "Interface Functions").

Example of a drying protocol with all selectable options.

Precisa PBM 60 *****	<i>Protocol title, will only be output in the mode printer.</i>
Date: 03/05/2024, Time: 11:06:01 AM	<i>Date and time if turned on</i>
Name : PBM 60 Radiator : Halogen / 50Hz Software : H00-0000 P02 Serialist : 9101422	<i>Balance ID if turned on</i>
Method : Boost/100C	<i>Method ID if enabled</i>
Number : 1	<i>Measuring series counter if switched on</i>
Id : 4006381333672	<i>Identification if entered using a USB keyboard or scanner</i>
Heating Mode : Boost / 3.0 Min Temperature : 100 C Stop Time : 10.0 min Auto Stop : 2/20 D/s StandBy Temp. : 40 C	<i>Dryer setup if switched on</i>
Weighing : + 2,186 g	<i>Starting weight is always output</i>
Mode Temp Time 100-0% B 105 C 1.0 min + 86.81 % B 140 C 2.0 min + 68.08 % B 140 C 3.0 min + 51.97 % 102 C 4.0 min + 44.05 % 98 C 5.0 min + 37.70 % 100 C 6.0 min + 29.84 % 100 C 7.0 min + 24.38 % 100 C 8.0 min + 22.64 % END 100 C 8.2 min + 22.60 %	<i>Measured value printout in the unit set for drying, only when print rate is turned on. In the "MODE PC" the individual values are displayed separately by tabs.</i>
100-0% : + 22.60 % Remainder : + 0.494 g Stop : Auto Stop Duration : 8.2 min	<i>Drying results are always output</i>
Last Balance Calibration : 04.03.2024 Last Temp. Calibration : 15.01.2024	<i>Date of last calibration if enabled</i>
Operator : PATTERN	<i>Operator ID if enabled</i>

5.3.4 Configuring the Application Menu

• SET APP. MENU	
	EDIT METHOD ON/OFF
	METHOD ID ON/OFF
	WEIGHING ON/OFF
	UNIT ON/OFF
	PRINT RATE ON/OFF
	STANDBY TEMP. ON/OFF
	STARTUP ON/OFF
	OPEN AUTO ON/OFF

The items activated under "SET APP. MENU" are displayed in the application menu and can be changed and set there (See chapter 5.3.19 "Application Menu Operation").

5.3.5 Configuring Ash Residue Program

This menu item is only available on PBM 66 devices. This moisture analyzer model includes a special ignition residue determination program.

• SET ASH RESIDUE	
	MODE MANUAL/AUTO
	MEMORY CHOICE ON/OFF

Under "SET GLOW LEVEL" you can define the recording of the weight and the calculation method. (See chapter 7 "Ash residue")

- With the memory choice "ON", four weights can be saved. With "OFF" only one weight can be stored.
- If "AUTO" is activated in mode, the dry weight is stored after each drying as a weight for determining the ash residue.

5.3.6 Balance Calibration

• SET BAL- ANCE CAL.		
	MODE OFF	<i>Disabled</i>
	EXTERNAL	<i>External</i>
	EXT.-DEF.	<i>External with freely de- fined weight (DEF. n.nnn g)</i>
	INTERNAL	<i>If int. weight prev.</i>
	AUTO	<i>If int. weight prev.</i>
DEF.	0.0000 g	<i>Calibration Weight for EXT. DEF. Mode</i>

For the calibration of the balance, see chapter 3.8 "Weight Calibration" and see chapter 9.3.1 "Calibrate the balance".

5.3.7 Temperature Adjustment

• TEMP. ADJUST- MENT	
TEMP. ADJUSTMENT	
ON	<i>Activate Temperature Adjustment</i>
OFF	

5.3.8 Stability

• SET STABILITY	
STABILITY	
HIGH	<i>Adjustment of the stability of the bal- ance (e.g. "High" provides more sta- ble values)</i>
MEDIUM	

■ 5 Operation

5.3.9 Quick-Start

• SET QUICKSTART

QUICK-START	ON OFF	<i>Setting the starting conditions</i>
-------------	------------------	--

QUICK-START OFF:

Drying starts when the "**START**" button is pressed as soon as a stable weighing value is reached.

QUICK-START ON:

Drying starts immediately when the "**START**" button is pressed or when the lid is closed. This makes it easier to dry highly volatile samples.

5.3.10 Refill

Refill ON:

Within 5 seconds of starting, the moisture analyzer hood can be opened again to add a solvent.

5.3.11 Interface Functions

• SET RS 232			
	BAUD RATE	300 600 1200 2400 4800 9600 19200 38400 57600	<i>Select baud rate</i>
	PARITY	7-EVEN-1STOP 7-ODD-1STOP 7-NO-2STOP 8-NO-1STOP	<i>Select Parity</i>

5 Operation ■

	8-EVEN-1STOP	
	8-ODD-1STOP	
	HANDSHAKE	NO
	XON-XOFF	
	HARDWARE	
		<i>Select hand-shake function</i>

With the help of the interface functions, the RS232/V24 interface of the device is matched to the interface of a peripheral device (See chapter 8 "Data Transfer").

MODE:

- "COM port": The USB connection behaves like a standard RS232 interface and appears on the PC in the COM interfaces.

Make sure that the baud rate, parity, and handshake settings match the settings in your PC.

- "HID port": Direct connection to a PC. The values transmitted by the balance are being handled by the PC as they were entered via a computer keyboard.

• SET USB HOST		
	Mode	<p>KEYBOARD <i>Keyboard</i></p> <p>SCANNER <i>Scanner Language</i></p> <p>FOOT SWITCH <i>Type</i></p> <p><i>Single</i></p> <p><i>Double</i></p> <p><i>Function</i></p> <p><i>Print</i></p> <p><i>Tare</i></p> <p><i>OFF</i></p> <p>USB STICK <i>Protection</i></p> <p><i>ON/OFF</i></p>

- "KEYBOARD": If a USB keyboard is connected.
- "SCANNER": If a USB scanner is connected.
Inputs via keyboard and scanner are assigned to the identifier "Id". "Id" is displayed in the info line of the balance display and inserted in the report output (see chapter 5.3.3.)
- "FOOT SWITCH": If a single or double USB foot button is required, is connected.
- "USB STICK": If a USB flash drive is connected.
Logs are saved as a text file "sssssss.TXT", where "sssssss" is the serial number of the balance, e.g. "9101422.TXT".

■ 5 Operation

5.3.12 Date and Time

• SET DATE AND TIME	DATE [DD.MM.YY] TIME [HH.MM.SS] FORMAT STANDARD/US	<i>Setting the date and time</i>
--------------------------------	---	--------------------------------------

! **NOTE**

In the event of a power outage, the clock continues to run. If this is not the case, the device's backup battery is exhausted and must be replaced by Precisa customer service.

5.3.13 Password

The two main menus and the drying parameters of the device can be protected against unwanted changes by means of a freely selectable, four-digit password.

- If password protection is deactivated, any operator can change the device at will.
- When password protection "Medium" is activated, the configuration menu is protected against unwanted changes.
- When password protection "High" is activated, the configuration, application menu, and drying parameters are protected.
- Only by deactivating password protection, by entering the correct password, can the locked menu items and parameters be changed again.

! **NOTE**

Password protection is disabled by default.

The **pre-programmed password** is: **7 9 1 4**

This password is the same for all Precisa devices and is always valid, in parallel with a password of your choice.

Write down your **personal password**.

• PASS-WORD

PASS-WORD	DATA PROTECTION OFF	<i>No protection</i>
	MEDIUM	<i>The configuration menu is protected</i>
	HIGH	<i>The configuration, application menu and drying parameters are protected</i>
	NEW PASSWORD_ _ _ _	<i>Enter a new password</i>

■ 5 Operation

To enable password protection, follow these steps:

Display	Key	Step
PASSWORD----	◀ ▶	Press repeatedly until "PASSWORD" is displayed.
PASSWORD 0000	◀◀ ▶▶	The first digit of the password flashes and can be changed.
PASSWORD 8000	◀ ▶	Press until the first digit of the password is set.
PASSWORD 8000	◀◀ ▶▶	The second digit flashes. Now the password can be completely entered.
PASSWORD 8000	◀◀ ▶▶	Confirm password.
PRIVACY OFF	◀ ▶	Data protection can be activated
PRIVACY OFF	◀◀ ▶▶	The indicator flashes and the data protection can be activated
DATA PROTECTION HIGH	◀◀ ▶▶	Enable data protection.
DATA PROTECTION HIGH	◀◀ ▶▶	Confirm data protection.

To change the password, follow these steps:

Display	Key	Step
PASSWORD NEW 7914	◀◀ ▶▶	Press until "PASSWORD" is displayed. Set new password as described above.

5.3.14 Anti-Theft Code

The device can be protected against theft by a freely selectable, four-digit numerical code:

- If the anti-theft coding is deactivated, the device can be switched on and operated again after a power interruption without entering a code.
- When anti-theft coding is enabled, the device will prompt you to enter the code after each voltage interruption.
- If the code is entered incorrectly, the device will be blocked.
- If the device is blocked, it must first be disconnected from the mains, then reconnected to the mains and unlocked by entering the correct code.
- After seven consecutive incorrect entries, the display "BLOCKED, CALL SERVICE" appears. In this case, only a Precisa service technician can unlock the device.



NOTE

Anti-theft coding is disabled as factory standard.

The **pre-programmed code** from the factory is: **8 9 3 7**

This code is the same for all Precisa devices. Therefore, for security reasons, always enter a code of your choice. Keep your **personal code** in a safe place.

• THEFTCODE

THEFTCODE ----	THEFT PROTECTION ON/ OFF	<i>Switch encoding on/ off</i>
	CODE NEW ----	<i>enter new code</i>

To enable anti-theft encoding, follow the same procedure as described for password protection.

5.3.15 Key tone

• KEYNOTE

KEYNOTE	OFF/ 1-9	<i>Key tone off and on (volume)</i>
---------	-----------------	-------------------------------------

■ 5 Operation

If the key tone is switched on, a short beep sounds every time a key is pressed.

5.3.16 Alert Tone

• ALERT TONE

ALERT TONE	OFF/1-9	<i>Alert sound off and on (volume)</i>
------------	---------	--

If the alert tone is switched on, a short beep will sound at each alert .

5.3.17 Backlight

• BACKLIGHT

BACKLIGHT	/1-9	<i>Brightness of the screen backlight)</i>
-----------	------	--

5.3.18 Set Configuration

• SET CONFIGURATION

	LOAD FACTORY CONFIG.	<i>Loading the factory configuration</i>
	LOAD APPLICATION CONFIG.	<i>Loading the user configuration</i>
	SAVE APPLICATION CONFIG.	<i>Saving the user configuration</i>



NOTE

Loading the factory configuration overwrites the current settings, but does not delete any saved user configurations.

5.3.19 Application Menu Operation

This section explains the structure of the application menu and its functions.

The structure of the application menu is dynamic and can be adjusted in the Configuration Menu (See chapter 5.3.4 "Application Menu Configuration").

If a menu item in the configuration menu is deactivated, it is not included in the current application menu.

- The menu item "**LOAD METHOD**" cannot be switched on/off, it is always included in the application menu.

Main Path	Definable functions
LOAD METHOD	<i>Setting a Stored Methods</i>
SAVE METHOD	<i>Save Method</i>
DELETE METHOD	<i>Deleting a Saved Method</i>
METHOD	<i>Entering the Method Label</i>
SETTING WEIGHT	<i>Definition of the weighing aid</i>
UNIT	<i>Choice of drying unit</i>
PRINT RATE	<i>Entering the interval time for the print rate Present when "PRINTRATE" is enabled in print format</i>
STANDBY TEMP.	<i>Definition of the Stand-By Temperature Function</i>
STARTUP	<i>Automatic start when the lid is closed</i>
AUTO OPENING.	<i>Setting the Automatic Hood Opening</i>

Display conventions:

- The factory-programmed settings are in **bold**.
- For a better overview, only the part of the menu tree that corresponds to this application is displayed for each function description.
- Explanations of the menu functions are printed in *italics*.

■ 5 Operation

5.4.1 Activation of the application menu

- Press «**MENU**» after the startup process has been completed to access the application menu.

5.4.2 Methods

The PBM 60 and PBM 60-HR moisture analyzers offer the ability to store 30 different methods. One method includes the settings for the drying program and the weighing aid.

The PBM 66 moisture analyzer contains two freely definable methods such as the PBM 60 or PBM 60-HR and three fixed, non-changeable methods, which are specially designed for drying sewage sludge:

Method	105	150/105	220/150/ 105
Interval 1			
• Temperature	105°C	150°C	220°C
• Stop Mode	10d/60s	20%	30%
Interval 2			
• Temperature		105°C	150°C
• Stop Mode		10d/60s	10%
Interval 3			
• Temperature			105°C
• Stop Mode			10d/60s

For each definable method, the following data is stored:

- Method name
- Weighing with:
 - Nominal Weight, Lower, Upper Weight Limit, Display Mode
- Drying program with:
 - Autostart setting (PBM60 only);
 - Drying Method
 - Drying Temperature
 - Stop Time
 - Auto Stop
 - Unit of the result

- Standby Temperature
- Auto hood opening

If the moisture analyzer is in weighing mode and the current weight is less than the minimum sample weight (< 0.2 g), the name of the currently loaded method (if available, alternating with the entered identifier "Id") is displayed in the info line.

In the configuration menu, under Set Application, the option "EDIT METHOD" is turned off (see chapter 5.3.4 "Configure Application Menu"), the menu items "SAVE METHOD" and "DELETE METHOD" are no longer active. This means that the stored methods are protected from modification. can only be worked with the methods that have already been saved.

All current methods and their settings can be accessed by pressing and holding the «PRINT» button until "PRINT APPLICATIONS" is displayed (see chapter 5.5.2 "The Print Button").

5.3.20 Save Method

• STORE METHOD

STORE METHOD	<i>Saving a Method</i>
--------------	------------------------

To save a method, do the following:

Set the drying parameters and weight for the desired method and give the method a name.

Activate the application menu by briefly pressing the "**MENU**" button.

Display


SAVE METHOD	« »	<i>Press repeatedly until "SAVE METHOD" appears.</i>
SAVE METHOD	« »	<i>If the method can be saved, the menu will automatically exit and the dryer will switch back to weighing mode.</i>

Key

Step

■ 5 Operation

The method cannot be saved if the method label is the same as a method that has already been saved:

Display	Key	Step
	 	<i>"YES" override existing method or "NO" save method under a new name.</i>
		

«| » *The method is saved and the dryer switches to weighing mode.*

or



«| » *The method name needs to be changed.*



Enter a new method name.



«| » *The method is saved and the dryer switches to weighing mode.*

If all memory spaces are occupied, no new method can be saved. You need to delete an old method first.

!	NOTE
A memory sequence can be cancelled at any time by pressing the "esc" key .	

5.3.21 Load Method

The arrow to the right takes you to the list of methods.

The up/down arrow displays the existing methods.

• LOAD METHOD		
LOAD METHOD	ttt... ttt... ttt... ttt... ttt...	<i>Choosing a Method</i> <i>Only the actual methods are shown!</i>

Only the currently saved methods are displayed in the menu. If no methods are saved, it is not possible to jump to the "LOAD METHOD" menu.

By pressing the " " button, the selected method is loaded and the dryer switches back to weighing mode.

5.3.22 Delete Method

The arrow to the right takes you to the list of methods.

The up/down arrow displays the existing methods.

■ 5 Operation

• CLEAR METHOD

CLEAR METHOD	ttt... ttt... ttt... ttt... ttt...	<i>Choosing a Method</i> <i>Only the existing methods are displayed!</i>
--------------	--	---

Only the currently saved methods are displayed in the menu. If no methods are saved, it is not possible to jump to the "DELETE METHOD" menu.

By pressing the " " button, the selected method is deleted and the dryer switches back to weighing mode.

5.3.23 Method Name

• METHOD

METHOD	ttt...	<i>Entering the Method Name</i>
--------	--------	---------------------------------

5.3.24 Weighing-In

• SET TARGET WEIGHT

WEIGHT CHECK	ON/OFF	<i>Switch check on/off</i>
NOM.	5,000 g	<i>Nominal weight</i>
TOLERANCE	g/%	<i>Tolerance abs./rel.</i>
TO MAXIMUM	6,000 g	<i>Upper Limit abs.</i>
TU MINIMUM	4,000 g	<i>Lower Limit abs.</i>
TOLERANCE+	10 %	<i>Upper Limit rel.</i>
TOLERANCE-	10 %	<i>Lower Limit rel.</i>
SET AD		
RANGE-		<i>0..TU / 50%.. TU</i>
SYMBOLS		<i>Permanent/stable</i>
TONE STABLE OK		<i>div. possibilities</i>

With the help of the "TARGET WEIGHT", you can weigh the sample weight exactly to its conformity with a defined reference value plus/minus permissible deviation.

With "Set Display" you can specify when (% of the lower limit) the display of the weighing aid is displayed and whether it is always visible or only when the weight is constant.

"+", "-" and " **II** " are active in the display.

If " **II** " lights up, the measured value is within the defined tolerances and the drying process can be started. If the sample weight is outside the weight tolerance, drying cannot be triggered. In this case, the weight tolerances are displayed as an error message.

5.3.25 Units

• UNIT	
UNIT	100-0%
	0-100%
	ATRO 100-999%
	ATRO 0-999%
	G/KG
	REMAINDER
	LOSS

In the menu item "UNIT" you can select the unit of the measurement results printed out in the protocol. The defined unit is also used for the expression of intermediate values. The unit for the printout can only be changed before a measurement and not during the measurement.

The selected unit is also used as a display unit but can be adjusted during and after the measurement (see chapter 5.5.3 "The Change Button").

The PBM 60-HR high-resolution moisture analyzer has 10 times higher readability for weight and 10 times higher readability for some moisture calculations.

Description / Calculation of Units

Character explanation of the variables used

- FG: Wet weight (weight value at the beginning of the measurement)
- TG: Dry weight (weight value at the end of the measurement)

Unit	Calculation
Dry matter in percentage:	$100 - 0\% = \frac{DW}{MW} * 100\%$
Humidity in percent:	$0 - 100\% = \frac{MW - DW}{MW} * 100\%$
ATRO Dry Matter:	$ATRO\ 100 - 999\% = \frac{MW}{DW} * 100\%$

Unit	Calculation
ATRO Humidity:	$ATRO\ 0 - 999\% = \frac{MW - DW}{DW} * 100\%$
Residual weight in g/kg [‰]:	$g / kg = \frac{DW}{MW} * 1000$
Residual weight in g:	RESIDUAL WEIGHT = DW
Humidity in g:	WEIGHT LOSS = MW - DW

Explanations of the ATRO units

The ATRO unit is used exclusively in the timber industry.

In practice, wood always has a different water content, which can change continuously. The water content has an influence on the combustion behaviour of the wood and the calorific value. During drying, the water evaporates. In open-air storage, the wood reaches the so-called air-dry state (lutro) of 15% to 20% water content. By heating it to temperatures above 100 °C, the moisture from the wood can be completely removed. This condition is called absolutely dry (ATRO).

The wood moisture content (ATRO) is the proportion of water contained in the wood, expressed as a percentage of the mass of the anhydrous wood and is calculated from the difference between fresh weight (FG) and dry weight (TG).

5.3.26 Print Rate

• PRINT RATE

PRINT RATE	1.0 MIN	<i>Print rate interval</i>
------------	----------------	----------------------------

With "PRINTRATE" the interval in which the intermediate results are printed is set. The print interval is from 0.1 ... 10.0 min adjustable in 0.1 min increments.

■ 5 Operation

5.3.27 Stand-By Temperature

• STANDBY TEMP.	
STANDBY TEMP. ON/OFF	<i>Switch stand-by temperature on/off</i>
TEMPERATURE 50°C	<i>Temperature value, only when stand-by temperature is turned on</i>

Regulates the temperature in the sample chamber to the set temperature value if the sample chamber is closed. The available temperature range ranges from 40°C ... 100°C. The circle in the display flashes as long as the stand-by temperature has not yet been reached. The indicator light turns red when the standby temperature is maintained.

5.3.28 Autostart

• AUTOSTART	
AUTOSTART ON/OFF	

If autostart is enabled, the measurement will start as soon as the sample chamber is closed. The prerequisite is that the moisture analyzer is prepared for a new measurement.

5.3.29 Auto Opening

• AUTO OPENING	
AUTO OPENING ON/OFF	<i>Opening temperature</i>
OPENING TEMP. 80°C 120°C 160°C DEF.	<i>Temperature</i>
DEF. TEMP. --- °C	<i>Temperature freely definable (50-230°C)</i>

Choose whether you want the hood to open automatically after the measurement. If so, enter the opening temperature.

5.5 Specially operated buttons

5.5.1 The Tare Button

- Make sure that no drying is running, i.e. the device is in weighing mode.
- **Triggering a buoyancy**
 - Short press «**T**»
 - A taring procedure is performed.
- **Select High Resolution Mode (HR)**
(This option is only available in HR models.)
 - Press and hold "**T**" until "HR MODE ON" or "HR MODE OFF" appears.
 - Release «**T**»
 - If "HR MODE OFF" is selected, the dryer works in low-resolution mode, which is 10 times less accurate than high-resolution mode.
- **Activating Calibration**
 - Press and hold «**T**» until "BALANCE CALIBRATION" is displayed.
 - Release «**T**»
 - The device performs a calibration according to the settings in the configuration menu and logs it by printout (See chapter 5.3.6 "Balance Calibration" and chapter 9.3.1 "Calibrate the Balance").
- **Activating a Temperature Calibration**
 - Press and hold «**T**» until "TEMP. CALIBRATION" is displayed.
 - Release «**T**».
 - The device performs a calibration according to the settings in the configuration menu and logs it by printout (See chapter 5.3.7 "Temperature Adjustment")



NOTE

Balance calibration is only active if it is enabled in the configuration menu.

A calibration or adjustment can be cancelled with "**ON/OFF**". This applies to the balance calibration as well as to the temperature calibration.

5.5.2 The Print button

- Make sure that no analysis is running, i.e. the device is in weighing mode.
- **Printing a single value or a protocol**
 - Press "**PRINT**" briefly
 - The drying protocol is printed. The protocol of the last measurement can be printed out until the start of a new drying process. The subsequently printed protocol does not contain any intermediate results. Otherwise, it is identical to the drying protocol that is printed out during the measurement. If no drying has been carried out since the device was started, the weight value is printed.
- **Printing statistics (PBM 60, PBM 60-HR only)**
 - Press «**PRINT**» until "PRINT STATISTICS" is displayed
 - Release «**PRINT**».
 - The statistics are printed out (see chapter 6.4 "Statistics (PBM 60, PBM 60-HR)")
- **Reset the counter to 1 (PBM 66 only)**
 - Press «**PRINT**» until "PRINT COUNTER" is displayed
 - Release «**PRINT**».
 - The counter resets to 1
- **Printing Device Settings**
 - Press and hold «**PRINT**» until «PRINT STATUS» is displayed
 - Release «**PRINT**». The device settings will be printed.

Status:
Date: 04/03/2024, Time: 16:12:39 Name : PBM 60 Radiator : Halogen / 50Hz Software : H00-0000 P02 Serialist : 9101422
Expression: Print format: Date and time : on Balance ID : on Method ID : off Numerator : on Dryer Setup : on Printrate : off Operator ID : off Kal.Info : on Print Rate : 1.0 min Operator : Mode :Printer

Status Print of Settings.

Device Identification

Drying Protocol Settings



Glow level: Mode : manual Memory Choice : on	<i>Ignition Residue Determination Settings (PBM 66 only)</i>
Calibration: Mode : external Defined weight : 0.0000 g	<i>Balance Calibration Settings</i>
Temp. Just. : off	<i>Temperature Calibration Settings</i>
Stability : high	<i>Stability Control</i>
RS 232: Baud rate : 9 6 0 0 Parity: : 8-no-1stop Handshake : no	<i>Interface settings RS 232</i>
USB Device: Mode : COM port Baud rate : 9600 Parity : 8-no-1stop Handshake : no	<i>Interface Settings USB Device</i>
USB Host: Mode : Keyboard Keyboard language : English	<i>Interface Settings USB Host</i>
Privacy : off Anti-theft : off	<i>Security</i>
Key tone : 6	<i>Key Tone Volume</i>
NOTE tone : 6	<i>Alert Sound Volume</i>

• Printing the application settings

- Press and hold «**PRINT**» until "PRINT APPLICATIONS" is displayed
- Release «**PRINT**»
- The application settings and all settings of the currently saved methods are printed.

Applications :	<i>Application printout of settings and saved methods.</i>
Dryer Setup : Heating Mode : Standard Time Boost : 3.0 min Time Ramp : 4.0 min Temperature : 105 C Time Stop : Off Time : 10.0 min Auto Stop : Digit/Time Digit/Time : 2/20 D/s Startup : off Standby Temp : off Temperature : 40 C Unit : 100-0% Auto. Opening : on Opening Temperature : 160 C	<i>Current Drying Parameter Settings</i>
Weighing: Test Weight : off Nominal : 5.000 g Tol. : g TO : 6.000 g TU : 4.000 g Display:...	<i>Current Weight Settings</i>

5 Operation

Method : TEST Smooth Dryer Setup :

Heating Mode	: Smooth
Time Boost	: 3.0 min
Time Ramp	: 4.0 min
Temperature	: 100 C
Time Stop	: on
Time	: 25.0 min
Auto Stop	: off
Startup	: off
Standby Temp	: on
Temperature	: 40 C
Unit	: 100-0%

Weighing:

Test Weight	: on
Nominal	: 6.000 g
Tol.	: g
TO	: 6.000 g
TU	: 4.000 g
Display:...	

Settings of the first method. With the PBM 66 moisture analyzer, only the definable methods are printed.

Method : TEST Boost Dryer Setup :

Heating Mode	: Boost
Temperature	: 140 C
Boost Time	: 1.0 min:
Time Ramp	: 4.0 min

Temperature	
Time Stop	: off
Time	: 10.0 min
Auto Stop	: AdaptStop

Startup	: off
Standby Temp	: off
Temperature	: 40 C
Unit	: 100-0%

Weighing:

Test Weight	: on
Nominal	: 3,500 g

Tol.	g
	6,000 g
TO	4,000 g

TU

Display:...

etc....

*Second Method Settings
(all saved methods will be printed)*

5.5.3 The Change button

• Unit Switching

- If drying is in progress, the displayed unit can be switched by pressing " ". Once a drying process has been completed, the drying result can be displayed in all existing units by pressing " " until a new drying process is started.
- Release « » when the unit you want to switch to is displayed.

5.5.4 The Start/Stop button

• Manual start of a drying process

- Make sure that there is no drying running, i.e. the device is in weighing mode.
- Short press «**START/STOP**»
- The measurement starts.

• Manual stop of a drying process

- Drying is in progress.
- Short press «**START/STOP**»
- The measurement is stopped.

• Statistics Info (PBM 60, PBM 60-HR only)

- Press «**START/STOP**» until "STATISTICS INFO" is displayed
- Release «**START/STOP**»

• Reset statistics (PBM 60, PBM 60-HR only)

- Press «**START/STOP**» until "RESET STATISTICS" is displayed.

- Let go of «**START/STOP**».

• Ash residue determination

- Make sure that there is no drying running, i.e. the device is in weighing mode.
- Press «**START/STOP**» until "GLOW LEVEL" is displayed.
- Let go of «**START/STOP**».
- The glow residue determination program is started. (See chapter. 7 "Ash residue")

6 Moisture determination

The moisture analyzer is used to quickly and reliably determine the moisture content of liquid, porous and solid materials using the thermogravimetry method.

6.1 Basics

Moisture is understood not only to mean water, but also to all substances that evaporate when heated. In addition to water, this also includes ,

- Fats
- Oils
- Alcohol
- Solvent
- etc...

There are various methods to determine the moisture content of a material.

The one used in the moisture analyzer is thermogravimetry. In this method, the sample is weighed before and after heating in order to determine the moisture content from the difference.

The conventional drying oven method works on the same principle, except that with this method the measuring time takes much longer. In the drying oven method, the sample is heated by a hot stream of air from its outside to the inside to remove the moisture.

In the case of the halogen radiation used in the moisture analyzer, the radiation mainly penetrates the sample where it is converted into heat energy, heating the sample from the inside out. A small portion of the halogen radiation is reflected by the sample; this reflection is lower in dark samples than in light samples. The penetration depth of the halogen radiation depends on the permeability of the sample. In the case of low-permeability samples, the halogen radiation only penetrates the upper layers of the sample, which may lead to incomplete drying, charring or combustion. Consequently, the sample preparation is extremely important.

■ 6 Moisture determination

6.1.1 Adjustment to the existing measurement methods

Often, the moisture analyzer replaces another drying method (e.g. the drying oven), as the device achieves shorter measuring times with simpler operation. For this reason, the conventional measurement method must be matched to the moisture analyzer in order to achieve comparable results.

- Performing Parallel Measurement
Lower temperature setting for the moisture analyzer than for the drying oven method
- The result of the moisture analyzer does not match the reference
 - Repeat Measurement with changed temperature setting
 - Vary the switch-off criterion
- Adjustment with calibration curve or factor

6.2 Sample

Prepare only one sample at a time for measurement. This prevents the sample from exchanging moisture with the environment. If several samples need to be taken at the same time, they should be packed in airtight containers so that they do not change during storage.

Spread the sample **evenly** and **thinly** over the sample tray to achieve reproducible results.

Uneven application leads to an inhomogeneous heat distribution in the sample to be dried, which results in incomplete drying or the extension of the measurement time. As a result of an accumulation of the sample, there is greater heating at the upper layers, which results in burns or incrustations. The high layer thickness or possible encrustation makes it impossible for moisture to escape from the sample. This residual moisture means that measurement results achieved this way are not verifiable and reproducible.

Solids:

- Distribute powdery and granular samples evenly on sample pan
- Crush coarse-grained samples with a mortar or grinder. When crushing the sample, avoid any use of heat, as this will result in moisture loss.

Liquids:

- For liquids, pastes or melting samples, it is recommended to use the fiberglass filter. The fiberglass filter has the following advantages:
 - Uniform distribution due to capillary effect
 - No formation of drops
 - Fast evaporation due to larger surface area

6.2.1 Preventing sample encrustation

To prevent the sample from crusting, additional solvent can be added to the sample after the measurement has started. The solvent added has no impact on the final result of the measurement. To allow filling immediately after the start, the option "REFILL" must be activated in the configuration menu.

- Start the measurement, automatically or by pressing the «**START/STOP**» button.
- Within 5 seconds after starting, the dryer hood can be opened again. During this time, the text "ADD SOLVENT" will be displayed in the info line of the display.
- After opening the sample chamber, you can add additional solvent at any time until the hood is closed.

■ 6 Moisture determination

Once the dryer hood is closed, the measurement is continued. In the info line of the display, "START HOOD CLOSED" is displayed.

If the **"START/STOP"** button is pressed, the measurement is aborted.



NOTE

The additional solvent is taken into account in the measured value printout, as intermediate values are calculated from the current weight value.

However, this has no influence on the drying result, as the solvent is completely dried away.

6.3 Setting Drying Parameters

The drying parameter setting is started with the four function keys below the display.



Each of the four function keys starts the input of the respective drying parameter. The input or modification of the respective parameter is designed in the same way as the operation of the menus. (See chapter 5.1 "Operating Principle of Menu Control"), except that in each case only the current parameter can be changed.

6.3.1 Heating program



This function key starts the selection of the heating program.

Three heating programs are available to determine the moisture content of the material:


- Standard Drying
- Boost Drying
- Smooth drying

• HEATING PROGRAM		
BOOST TIME	3.00 MIN	<i>Only adjustable on PBM 60 / PBM 60 HR (not on PBM66)</i>
RAMP TIME	4.00 MIN	
HEATING MODE		<i>Select heating program</i>
STANDARD		
BOOST	BOOST TIME	3.00 min
SMOOTH	RAMP TIME	4.00 min

Standard Drying

The drying temperature is set by the user. The final temperature is approached with high heating power and kept constant with slight overshoot.

This program is used for most samples.




Boost Drying

The drying temperature is set by the user. During the first 3 minutes of drying, the target temperature is exceeded by 40% (for the PBM 60 and PBM 60-HR the duration is selectable from 0.1-99.9 min). At the end of this time, the temperature is reduced to the target temperature. The temperature is approached with a high heating capacity.

■ 6 Moisture determination


The maximum temperature reached during the boost is 230°C.
This program is used for samples with very high moisture content.



Smooth Drying

The drying temperature and ramp time are specified by the user. The final temperature is gently approached with low heating power.

This program is used for samples with low moisture content where there is a risk of burning.



6.3.2 Temperature



This function key is used to start the drying temperature input. The drying temperature can range from 50°C ... 230°C in 1°C increments. Temperatures above 200°C are automatically reduced to 200°C after 10 minutes.

• DRYING TEMPERATURE	
TEMPERATURE 105°C	<i>Temperature Input</i>

The drying temperature for drying with the moisture analyzer can be set lower than for drying with the drying oven method.

6.3.3 Timer Stop



This function key is used to define the drying time. If Time Stop is enabled, the measurement will end after the set time. The time can vary from 1.0 min ... 240.0 min, in 0.1 min increments.

• DRYING	
STOP TIME 10.0 MIN	<i>Only when time-stop is activated</i>
TIME STOP ON/OFF	

■ 6 Moisture determination

6.3.4 Shutdown Criteria



This function key starts the definition of the shutdown criterion for the measurement.

PBM 60, PBM 60-HR

Two freely definable stop modes are available according to the principle of "digit per time" or "% of weight per time". In addition, there is the automatic stop mode "ADAPTSTOP".

• STOPMODE		
DIGIT/TIME	2/20	<i>If Digit/Time is selected</i>
%/TIME	0.2/20	<i>If %/Time selected</i>
AUTO STOP	DIGIT/TIME %/TIME ADAPTSTOP OFF	

PBM 66


The PBM 66 is available with five fixed and one freely definable stop mode according to the "digit per time" principle. In addition, there is the automatic stop mode "ADAPTSTOP".

• STOPMODE		
AUTO STOP	01/20 D/S	<i>Only if DEF. is selected</i>
AUTO STOP	OFF 2/10 2/20 2/30 2/60 10/60 ADAPTSTOP DEF.	

Switch-off criterion digit per time

Drying is switched off as soon as the weight loss is less than the number of digits set in the set time. The weight loss must have once been greater than the cut-off criterion.

With the freely definable mode, you can choose from 1 ... 99 digits in 1-digit increments and from 10 to 90 seconds in 10 second increments.



A digit is the smallest change in measured value that can be displayed by the moisture analyzer.

PBM 60, PBM 66: 1Digit = 1mg

PBM 60-HR: 1Digit = 0.1 mg

Shutdown criterion % per time

Drying is switched off as soon as the weight loss is less than the selected percentages in relation to the weight in the set time. The weight loss must have once been greater than the cut-off criterion.

The percentages can be set from 0.1% to 99.9% in 0.1% increments and the time from 10 to 90 seconds in 10 second increments.

ADAPTSTOP

Is a fully automatic stop mode that determines the shutdown time based on the drying process.

■ 6 Moisture determination

6.4 Statistics (PBM 60, PBM 60-HR)

The results of a series of measurements are automatically transferred to the statistical evaluation.

To retrieve the information, make sure that there is no drying in progress, i.e. the device is in weighing mode.

- Press «**START/STOP**» until "STATS INFO" is displayed
- Release «**START/STOP**»
- Switch between the statistical values using "↑" or "↓"

• STATISTICS INFO	
MEDIUM	<i>Mean Value</i>
MAX	<i>Largest Value</i>
MIN	<i>Lowest Value</i>
STDDEV	<i>Standard deviation</i>
STDDEV %	<i>Relative standard deviation</i>
1 =	<i>Value 1</i>
2 =	<i>Value 2 etc.</i>

6.4.1 Printing the statistics

Exit the statistics with «**esc**»

- Keep «**PRINT**» pressed until "PRINT STATISTICS" is displayed
- Release «**PRINT**»

The statistics are printed:

Precisa	PBM 60 *****	<i>Protocol title, is only output in the mode printer</i>
Date: 04.03.2024	Time 11:06:01	<i>Date and time if turned on</i>
Name	: PBM 60	<i>Balance ID if turned on</i>
Spotlight	: Halogen / 50Hz	
Software	: H00-0000 P02	
Serialist	: 9101422	
Method	: 105	
Date	: 28.02.2024	
Values	: 4	
Unit	: 100-0%	
Mean Maximum	: 57.36 %	<i>Statistics</i>
Minimum	: 57.39 %	
Stddev	: 57.34 %	
Stddev %	: 0.02 %	
Stddev %	: 0.042 %	

1	: 57.34 %
2	: 57.38 %
3	: 57.34 %
4	: 57.39 %
Last weight calibration: 02.03.2024	
Last temperature calibration : 13/01/2024	

*Individual values**Calibration Information*

6.4.2 Reset the statistics

The statistics start again at:

- Restarting the device
- Changing the Method
- Manual reset:
 - Reset statistics (PBM 60, PBM 60 HR only)
 - Press and hold «**START/STOP**» until "RESET STATISTICS" is displayed
 - Release «**START/STOP**».

■ 7 Annealing residue

7 Ash residue program

 STOP	Start/stop button	
	START/STOP DRYING	<i>Not displayed</i>
	STATISTICS INFO	<i>Only PBM 60, PBM 60-HR</i>
	RESET STATISTICS	<i>Only PBM 60, PBM 60-HR</i>
	ASH RESIDUE	

The determination method of ash residue is different for the PBM 60, PBM 60-HR and PBM 66 models.

When determining the ash residue, the dried sample is used as a weight. This sample is burned in an external furnace and then weighed back in the moisture analyzer.

Calculation of the ash residue:

Unit	Calculation
Ash residue in percentage:	$\text{Glührückstand} = \frac{\text{Rückwaage}}{\text{Einwaage}} * 100\%$

After calculating the ash residue, a report is printed, which is identical for the PBM 60, PBM 60-HR and PBM 66 models.

Ignition residue protocol with all selectable options.

Precisa PBM 60 *****	<i>Protocol title, will only be output in the mode printer.</i>
Date: 03/04/2024, Time: 11:06:01	<i>Date and time if turned on</i>
Name : PBM 60 Radiator : Halogen / 50Hz Software : H00-0000 P02 Series : 9101422	<i>Balance ID if turned on</i>
Determination of the glow level: Weighing : 15.000 g Back Balance : 9.500 g Incandescent : 63.33 %	<i>Ignition residue calculation</i>
Operator : PATTERN	<i>Operator ID if enabled</i>



7.1 Ignition residue determination for PBM 60 and PBM 60-HR

With the moisture analyzers PBM 60 and PBM 60-HR, only one weight can be stored. It is also not possible to set parameters for the determination of the ignition residue.

Determining Ash residue

Display

Key

Step

«**START**
»

Press until "ASH RESIDUE " is displayed.
Release the button.

+ 15.000 g
ORIGINAL 0.000 g

Add the weight to the balance.

+ 15.000 g
ORIGINAL 15,000 g

«**↵**»

The weight is saved

The weight remains stored in the device until an ignition residue calculation has been carried out

By pressing the "**esc**" key, the ignition residue calculation can be exited.

+ 0.000 g
RESIDUAL 0.000 g

«**↵**»

If a weighing is saved, the residual weight is required when the ash residue determination is restarted. (Select original weight or residual weight)

or
«**↵**»

+ 0.000 g
ORIGINAL 0.000 g

Add the residual sample to the balance.

+ 9.500 g
RESIDUAL 0.000 g

+ 63.33 %
ASH RESIDUE

«**↵**»

Save the residual weight and calculate the ash residue.

The ash residue is automatically calculated and printed.

■ 7 Annealing residue



NOTE

Tare the instrument with an empty sample pan before starting the ash residue determination.

7.2 Ash residue PBM 66

With the PBM 66 moisture analyzer, up to four weights can be stored (memory selection on), which are not deleted after determination of the ash residue. If the device is switched off, the stored weights will be lost.

If "**MEMORY CHOICE ON**" is selected, up to four tare and initial weights can be stored.

If "**MEMORY CHOICE OFF**" is selected, only one initial sample weight can be stored. This means that the instrument can only be used after the reweighing is completed, as the tare weight has not been stored



NOTE

If "MEMORY CHOICE OFF", the moisture analyzer cannot be re-zeroed between the initial sample weight and the ash determination.

If the mode "MODE AUTO" is activated, the dry weight is automatically saved as the initial sample weight for the ash residue determination. The initial sample weight can also be entered manually.

If the "MODE MANUAL" is activated, the initial sample weight can only be entered by starting the ash residue determination.

If "MEMORY CHOICE ON", together with "MODE MANUAL", the moisture analyzer can be used for other moisture determination routines between the initial sample weight and the corresponding re-weighing value (See chapter 5.3.5 "Ash residue configure")

7.2.1 Ash residue of the dessicated samples

If the dried samples are directly incinerated without transferring them to other crucibles, work in **auto** mode (configuration).

Tare and dry weight (result of drying) are stored and are available for the calculation of the ash residue.



The ash residue is calculated using the dry mass.

Ash residue:

Ensure that no moisture analysis is taking place, i.e. that the instrument is in weighing mode.

Display	Key	Step
<div style="border: 1px solid black; padding: 5px; text-align: center;"> ----- -1- -2- -3- -4- </div>	«START»	Weighing Numbers are displayed Select the weight number 1 (or 2-4)
<div style="border: 1px solid black; padding: 5px;"> + 0.000 g TARE </div>	«T»	Tare the device without load
<div style="border: 1px solid black; padding: 5px;"> + 2.535 g PAN TARING </div>	«T»	Place empty pan 1 on top. Measure tare value 1.
<div style="border: 1px solid black; padding: 5px;"> + 7.147 g PLACE SAMPLE </div>		Place the sample into the weighing pan.

Start the drying process by closing the hood.

The result will be printed automatically

<div style="border: 1px solid black; padding: 5px;"> + 726.5 gkg DURATION 3.5 MIN </div>	«esc»	Back to Weighing Mode
---	-------	-----------------------

Repeat these steps for all samples (up to 4 samples)

Ash the samples externally

Reweighing the ashed samples

<div style="border: 1px solid black; padding: 5px; text-align: center;"> ----- -1- -2- -3- -4- </div>	«START»	Press and hold until "ASH RESI- DUE " is displayed. Release the button. Select the return balance of sample 1 (or 2-4)
<div style="border: 1px solid black; padding: 5px;"> + 0.000 g ORIGINAL </div>	«↓»	Change to residual.
<div style="border: 1px solid black; padding: 5px;"> + 0.000 g RESIDUAL </div>	«↵»	Confirm the choice

■ 7 Annealing residue

Display	Key	Step
<div style="border: 1px solid black; padding: 5px;"> + 0.000 g TARE </div>	«T»	<i>Tare the device without load</i>
<div style="border: 1px solid black; padding: 5px;"> + 0.235 g RESIDUAL 0.000 g </div>		<i>Place the pan with the ash onto the balance</i>
<div style="border: 1px solid black; padding: 5px;"> + 4.52 % ASH RESIDUE </div>	« »	<i>Adopt the weighing value</i>

The ash residue is automatically calculated and printed.

If "MEMORY CHOICE OFF", the process will run for only one sample. Selection of the initial sample weight number and re-zero are not necessary.

7.2.2 Ash residue with new tare weight

If the dry mass is transferred to a new tare vessel before ashing, or if undried samples are used, "MODE MANUAL" or "MODE AUTO" should be used.

Display	Key	Step
	«START»	<i>Press and hold until "ASH RESIDUE" is displayed. Release the button.</i>
<div style="border: 1px solid black; padding: 5px;"> ----- -1- -2- -3- -4- </div>	« » «⇒»	<i>Select the weight number 1 (or 2-4)</i>
<div style="border: 1px solid black; padding: 5px;"> + 0.000 g ORIGINAL </div>	«⇐»	<i>Confirm the choice</i>
<div style="border: 1px solid black; padding: 5px;"> + 0.000 g TARE </div>	«T»	<i>Tare the device without load.</i>
<div style="border: 1px solid black; padding: 5px;"> + 2.535 g TARE PAN </div>	«T»	<i>Place empty pan 1 on top. Measure tare value 1.</i>



Display	Key	Step
+ 4.809 G ORIGINAL 0,000	«»	<i>Pour the sample into the pan. Confirm original weight</i>
+ 4.809 g ORIGINAL 4.609		

Repeat for all samples (back to the weighing mode with «**esc**»)
 Ash the samples externally

Reweighting the ashed samples

	« START »	<i>Press until "ASH RESIDUE" is displayed. Release the button.</i>
-1- -2- -3- -4-	«» «»	<i>Select the return balance of sample 1 (or 2-4)</i>
+ 0.000 g ORIGINAL	«»	<i>Change to residual.</i>
+ 0.000 g RESIDUAL	«»	<i>Confirm choice</i>
+ 0.000 g Tare	« T »	<i>Tare the device without load</i>
+ 0.235 g RESIDUAL 0.000 g		<i>Place the pan with the ash onto the balance</i>
+ 5.19 % ASH RESIDUE	«»	<i>Confirm weighing</i>

The ash residue is automatically calculated and printed.

If "MEMORY CHOICE OFF", the process will run for only one sample.
 Selection of the initial sample weight number and re-zero are not necessary.

8 Data transfer

For data transfers to peripheral devices, the moisture analyzer is equipped with an RS232/V24 interface and an USB interface.

Before data transfer, the RS232 interface or USB interface must be matched with the peripheral device in the configuration menu of the instrument (see chapter 5.3.11).

• Handshake

The handshake is factory-set to "NO". It can be set to software handshake "XON/XOFF" or to hardware handshake.

• Baud rate

Possible baud rates: 300, 600, 1200, 2400, 4800, 9600, 19200, 38400, 57600 baud.

• Parity

Possible parity: 7-even-1 stop, 7-odd-1 stop, 7-no-2 stop, 8-no-1 stop, 8-even-1 stop, 8-odd-1 stop

Pos.	0	1	2	3	4	5	6	7	8	9	10
7-even-1	SB	1. DA	2.DA	3. DA	4. DA	5. DA	6. DA	7.DA	PB	SP	-
7-odd-1	SB	1. DA	2.DA	3. DA	4. DA	5. DA	6. DA	7.DA	PB	SP	-
7-no-2	SB	1. DA	2.DA	3. DA	4. DA	5. DA	6. DA	7.DA	1.SP	2. SP	-
8-no-1	SB	1. DA	2.DA	3. DA	4. DA	5. DA	6. DA	7.DA	8. DA	SP	-
8-even-1	SB	1. DA	2.DA	3. DA	4. DA	5. DA	6. DA	7.DA	8. DA	PB	SP
8-odd-1	SB	1. DA	2.DA	3. DA	4. DA	5. DA	6. DA	7.DA	8. DA	PB	SP

SB: Start Bit PB: Parity Bit
 DA: Data Bit SP: Stop Bit

• Display

S D7 D6 D5 D4 D3 D2 D1 D0 U U U

The data is transmitted in ASCII code:

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
B	B	B	S	D7	D6	D5	D4	D3	D2	D1	DP	D0	B	U	...	CR	LF

B	Blank (space)
S	Prefix (+, -, space)
DP	Decimal point
D0... D7	Digits
U ...	Unit (only if weight is stable, otherwise no unit is sent)
CR	Carriage return
LF	Line feed



NOTE

Unused positions are filled with spaces.
The decimal point DP can be between D0 and D7.

8.1 Connection Scheme

• Standard duplex connection

Moisture analyzer	DB9	DB25 / DB9	Peripheral
RS 232 out	2	→ 3 / 2	RS 232 in
RS 232 in	3	← 2 / 3	RS 232 out
GND	5	— 7 / 5	GND

• Standard duplex connection with additional hardware handshake in the peripheral instrument

Moisture analyzer	DB9	DB25 / DB9	Peripheral
RS 232 out	2	→ 3 / 2	RS 232 in
RS 232 in	3	← 2 / 3	RS 232 out
GND	5	— 7 / 5	GND
CTS	4	← 20 / 4	DTR
DTR	8	→ 5 / 8	CTS

8.2 Remote Control Commands

Command	Function
ACKn	Acknowledgement n=0 off; n=1 on
CAL	Start Calibration (only if EXT is selected)
DN	Reset Weight Display
D.....	Describe weight display (right-aligned)
@N	Reset info display
@.....	Describe info display
N	Reset instrument
OFF	Turn off the instrument
ON	Turn on the instrument
PCxxxx	Enter anti-theft code
PDT	Print date and time
PRT	Start printing (press « PRINT » button)
SHH	Trigger Status Print
Pn (ttt.t)	Setting print mode n=0 Single print each value (unstable) n=1 Single print stable value (stable) n=2 Print after load change n=3 Print after each integration time n=4 Print with time base in s (ttt.t)



Command	Function
SDTtmmjj hhmmss	Set Date and Time (German: (Tag, Monat, Jahr, Stunde, Minute, Sekunde))
SDTmmddy hhmmss	Set Date and Time (English: Month, Day, Year, Hour, Minutes, Seconds)
T (ttt)	Tare or set taring to a specific value
ZERO	Set the instrument to 0 (if weight is stable and within the zero setting range)
Rttt	Regulates the heating to the desired temperature (50°C ... 230°C)
ROFF	Switch off heating
PWT (ttt.t)	Print weight value and temperature value Print with time base in sec. (ttt.t) (switch off by sending PWT)

8.2.1 Examples of remote control of the device



NOTE

Each remote control command must be completed with «CR» «LF». The commands will be acknowledged on request.

Input	Description of the triggered function
D - - - - -	Five dashes are displayed
DTEST123	Displaying: tESt123
D	The display is dark
T10	-10,000 g (tare set to 10g)
T1	-1,000 g (tare set to 1g)
T	Instrument is being tared
R100	Adjusts the temperature to 100 °C

9 Service

9.1 Maintenance and care

The moisture analyzer must be handled with care and cleaned regularly. It is a precision instrument.



DANGER

For maintenance work, the device must be disconnected from the power supply. It must also be ensured that the device cannot be reconnected to the mains by third parties during the work.

When cleaning, make sure that no liquid penetrates the device. If liquid is spilled on the device, it must be disconnected from the power supply immediately. The moisture analyzer must not be operated again until it has been checked by a Precisa service technician.

The connections on the back of the device must not come into contact with liquids.

Regularly remove the weighing pan and weighing pan holder and remove any dirt or dust under the weighing pan and on the balance housing with a soft brush or a soft, lint-free cloth moistened with mild soapy water.

The weighing pan and the holder can be cleaned under running water. Make sure that both parts are completely dry before remounting them on the device.




WARNING

Never use solvents, acids, alkalis, paint thinners, scouring powders or other harsh or corrosive chemicals for cleaning, as these substances can attack and damage the surfaces of the device housing.

Regular maintenance of the moisture analyzer by your Precisa service representative guarantees its unrestricted function and reliability for years and extends the service life of the device.


9.2 Replacing the mains fuse

If the display remains dark after switching on the device, in most cases the device fuse is defective and must be replaced.



DANGER

To replace the fuses, the device must be unplugged.



- Use a screwdriver to unscrew the fuse holder on the back of the device anticlockwise.
- Replace the defective fuse with a new one:
 - 230 Volt variant:
T 3.15 A, 230 V, 5x20 mm
 - 115 Volt variant:
T 6.3 A, 115 V, 5x20 mm
- If the device still does not work after changing the fuse, please contact Precisa Service Center



DANGER

Under no circumstances should you use other fuses or attempt to bridge the fuse.

9.3 Calibration, adjustment

The calibration of the moisture analyzer is done in the configuration menu (See chapter 3.8 "Weight Calibration" and chapter 5.3.6 "Balance Calibration").



NOTE

By pressing «ON/OFF», the balance calibration and temperature calibration can be cancelled at any time.

9.3.1 Calibrating the balance

Possible types of balance calibration:

- External calibration using ICM (Intelligent Calibration Mode)
- External calibration with freely selectable weight
- Internal Calibration (optional)
- Automatic internal calibration (optional)

External calibration using ICM

For the moisture analyzer, calibration weights can be used in 10g increments, where the calibration weights must correspond to the precision of the instrument.

For external calibration using ICM, in the configuration menu (See chapter 5.3.6 "Balance Calibration") must be selected "SET CALIBRATION MODE EXTERNAL".

Display

+0.000 g

Key

Step

Balance is in weighing mode.

+0.000 g
BALANCE CALIBRATION

«T»

Press and hold the button until "BALANCE CALIBRATION" is displayed.

- - 0000 g

A zero point measurement is carried out (0000 g is displayed flashing)

- - 50 g

After the zero point measurement, the display flashes with the recommended calibration weight

- - 50 g

Place calibration weight. The display continues to flash

+50.000 g

Calibration is complete when the display stops flashing (The exact value is displayed)

External calibration with freely selectable weight

For an external calibration with freely definable weight, the configuration menu (see Chapter 5.3.6 "Balance Calibration") "SET CALIBRATION MODE EXT.-DEF." can be selected.

After that, the RMS value of the calibration weight (DEF. n.nnnn g) must be entered with up to ten times the accuracy of the instrument.

	NOTE
If the calibration is carried out with the free weight, only this weight may be used.	

Follow these steps:

Display

+0.000 g

Key

Step

Dryer is in weighing mode.

+0.000 g
BALANCE CALIBRATION

«T»

Press the button until "BALANCE CALIBRATION" is displayed.

- - 0000 g

A zero point measurement is carried out (0000 g is displayed flashing)

■ 9 Service

Display

-- 22 g

-- 22 g

+22.125 g

Key

Step

After the zero point measurement, the indicator flashes with the calibration weight previously entered.

Apply calibration weight. The indicator continues to flash rapidly.

When the indicator stops flashing, the calibration is complete. (The exact value is displayed)

Internal Calibration

For an internal calibration with the built-in calibration weight, the configuration menu (see Chapter 5.3.6 "Balance Calibration") "SET CALIBRATION INTERNAL MODE".

Follow these steps:

Display

+0.000 g

+0.000 g
BALANCE CALIBRATION

- 0000 g
CALIBRATE INTERNALLY

--Int
CALIBRATE INTERNALLY

Key

Step

Moisture Analyzer is in weighing mode.

«T»

Press the button until "BALANCE CALIBRATION" is displayed.

A zero point measurement is carried out (0000 g is displayed flashing)

The built-in calibration weight is measured.

Automatic internal calibration

For automatic calibration with the built-in calibration weight, the configuration menu (see Chapter 5.3.6 "Balance Calibration") "SET CALIBRATION AUTO MODE".

The balance now calibrates itself automatically every 24 hours, depending on the definition in the configuration menu "SET CALIBRATION MODE AUTO AUTOCAL. - TIME" (e.g. 6 h for 06.00 in the morning) and/or after any temperature change of 3 degrees Celsius.

Protocol printout of the calibration.

Calibration	Balance Calibration Protocol
Date: 03/04/2024, Time: 12:51:36 PM Name : PBM 60 Radiator : Halogen / 50Hz Software : H00-0000 P02 Serialist : 9101422	Time of calibration and instrument data
Calibration OK	Status of calibration
Operator :	Operator ID, if enabled under "SET PRINT FORMAT". (See chapter 5.3.3 "Configure Log Expression")


9.3.2 Temperature Adjustment

For a temperature adjustment to be carried out, the configuration menu (see chapter 5.3.7. "Temperature Adjustment") "TEMP. ADJUSTMENT".

Then follow these steps:

- Use the Temperature Calibration Kit, (see Chapter "Accessories").

Display



Step button

Moisture Analyzer is in weighing mode

■ 9 Service

+0,000 9
TEMP. CALIBRATION

«T» *Press the button until "TEMP. CALIBRATION" is displayed.*

T100 T160 START

«←» *Setting the lower temperature value for calibration.*

T100 T160 START

«→» *Setting the higher temperature value for calibration.*

It should be noted that the difference between the two temperature values is greater than 40°C.

T100 T160 START

«START» *When the temperature adjustment set is connected to the device*

TEMP 25°C 20.00MIN

*The temperature calibration is started.
The Moisture Analyzer heats up to the first temperature value.*

The info line shows the temperature measured by the Moisture Analyzer and the remaining time for temperature calibration. Heating up to a temperature takes 20 minutes.

TEMPERATURE 100°C

After 20 minutes, enter the temperature displayed on the thermometer of the temperature adjustment kit on the Moisture Analyzer.

TEMP 105°C 20.00MIN

The Moisture Analyzer heats up to the second temperature value.

TEMPERATURE 160°C

After another 20 minutes, please enter the temperature on the dryer as shown on the thermometer of the temperature adjustment kit.



Choose between "use this temperature measurement as an adjustment" or "use this temperature measurement as a calibration".

After selecting JUST or KAL, the temperature adjustment or calibration is completed and the corresponding protocol is printed.

Protocol printout of the adjustment

Temperature Adjustment	
Date: 03/04/2024, Time: 12:51:36 PM Name : PBM 60 Radiator : Halogen / 50Hz Software : H00-0000 P02 Series : 9101422	Time of temperature adjustment and device data
Thermometer:	Device designation of the temperature adjustment set
Temperature 100 C : 102 C Temperature 160 C : 161 C	Result of temperature adjustment
Adjustment carried out	Device has been temperature adjusted
Operator :	Operator ID, if enabled

Calibration protocol printout

Temperature Calibration	
Date: 03/04/2024, Time: 12:51:36 PM Name : PBM 60 Radiator : Halogen / 50Hz Software : H00-0000 P02 Series : 9101422	Time of temperature calibration and instrument data
Thermometer:	Device designation of the temperature adjustment set
Temperature 100 C : 99 C Temperature 160 C : 159 C	Temperature Calibration Result
Tolerance +/- 3 C Calibration passed	Temperature calibration successful The measured values are within the required limits
Operator :	Operator ID, if enabled

■ 9 Service

9.4 Firmware update

The latest firmware version of the instrument firmware can be downloaded from our website. The instructions for the update procedure are also available there.

9.5 Error

The device displays an error description in the info line.



NOTE

If an error occurs without a description of the error in the info line, a Precisa service technician must be contacted.

Error message	Cause
Starting value too small	<ul style="list-style-type: none"> The sample weight is too small (< 0.200 g). The sample weight must be greater than 0.200 g.
MINIMUM x.xxx g MAXIMUM x.xxx g	<ul style="list-style-type: none"> The sample weight is not within the tolerance of the weight.

9.5.1 Notes on troubleshooting

The following table lists malfunctions and their possible causes. If you are unable to resolve the fault using the table, please contact a Precisa service technician.

Fault	Possible causes
Weight indicator does not light up	<ul style="list-style-type: none"> Device is not turned on Power cord not plugged in Defective mains fuse
It's going to be "OL" displayed	<ul style="list-style-type: none"> The weighing range has been exceeded (indication of the maximum weighing range)
"UL" is displayed	<ul style="list-style-type: none"> The weighing range of the instrument is lower (sample tray or tray carrier is missing)
The weight display is constantly changing	<ul style="list-style-type: none"> Too much air flow at the device location The device support vibrates or fluctuating The sample dish is in contact with a foreign body The sample absorbs moisture The sample evaporates/vaporates/sublimates Sharp temperature changes in the sample
Measurement result is obviously wrong	<ul style="list-style-type: none"> The device was not tared correctly The device is not leveled correctly The calibration is no longer correct Sharp temperature changes in the sample
Configuration menu cannot be changed	<ul style="list-style-type: none"> In the configuration menu, password lock is enabled

■ 9 Service

Fault	Possible causes
During calibration, the indicator flashes continuously	<ul style="list-style-type: none"> • The location of the device is too unstable (cancel calibration with "ON/OFF" and place the device in a more suitable location) • Use of an inaccurate calibration weight (only for external calibration)
The connected printer does not print	<ul style="list-style-type: none"> • The printer is not turned on • The data cable is defective or not connected • The interface settings do not match the moisture analyzer.
The printer prints incorrect characters	<ul style="list-style-type: none"> • The parity setting or baud rate of the interface does not match • The data cable is defective
Drying does not start	<ul style="list-style-type: none"> • The sample is not stable

10 Overview

10.1 Specifications

Specification	PBM 60 (-HR)	PBM 66
Heat source, radiator type	Halogen / Infra-red / Dark Radiator	Halogen / Infra-red / Dark Radiator
Weighing range [g] / readability [mg]	124 / 1 (0.1)	310 / 1
Drying:		
Readability [%]	0.01 (0.001)	0.01
Reproducibility at approx. 2 g [%]	0.1 (0.05)	0.1
Reproducibility at approx. 10g [%]	0.015 (0.01)	0.015
Sample weight [g]	0.2 - 124	0.2 - 310
Result Calculations:	100-0%, 0-100% ATRO 100-999%, ATRO 0-999%, G/KG, REMAINDER, LOSS	100-0%, 0-100% ATRO 100-999%, ATRO 0-999%, G/KG, REMAINDER, LOSS
Heating:		
Temperature range / step [°C]	50 - 230 / 1	50 - 230 / 1
Heating Methods	Standard, Boost, Smooth	Standard, Boost, Smooth
Intervals	Boost + 1	Boost + 1
Booster	+40%	+40%
Boost time [min.]	0.1 - 99.9	3.0
Ramp time [min.]	1.0 - 600.0	4.0
Shutdown criteria:		
Auto Stop [d/s]	selectable 1 - 99 / 10 - 90	5 fixed settings or selectable 1 - 99 / 10 - 90
Auto Stop [%/s]	selectable 0.1 - 99.9 / 10 - 90	-
Adaptstop	x	x
Timer Stop [min.]	0.1 - 240.0	0.1 - 240.0
Surveillance:		
Status indication (red/green)	x	x
Acoustic	x	x
Expression:		
GLP	x	x
Expression - Interval [min.]	0.1 - 10.0	0.1 - 10.0
Sample Numbering	x	x

■ 10 Overview

Specification	PBM 60 (-HR)	PBM 66
Storage capacity:		
Methods (with all settings)	30	2+ 3 fixed
User Texts	2	2
Service:		
"Easy access" sample holder	x	x
Display	LCD	LCD
Keyboard	10 buttons	10 buttons
Password	x	x
Special Features :		
Weighing with limits / weighing aid	x / x	x / x
Software Download and Update	x	x
Automatic hood opening	x / x	x / x
Adjustment:		
Balances (internal/external)	x	x
Temperature, fully automatic	at 100°C and 160°C	at 100°C and 160°C
Miscellaneous:		
Clock for date and time	x	x
Interface for PC and printer	RS232 USB B Device USB A Host	RS232 USB B Device USB A Host
Digital I/O	optional	optional
Theft protection	Code and mechanical	Code and mechanical
Connection:		
Line voltage	230V or 115V switchable by changing the heating unit (only possible with Precisa Service)	230V or 115V switchable by changing the heating unit (only possible with Precisa Service)
Mains frequency [Hz]	50 - 60	50 - 60
Power Consumption [W]	450	450
Dimensions:		
Housing dimensions (WxHxD) [mm]	201x177x332	210x170x332
Weight [kg]	6	6

■ 19 Menu trees

10.2 Menu Overview

10.2.1 Configuration Menu Tree

Press and hold the «MENU» button when switching on:

• SET DATA PRINT			
	SET PRINT FORMAT	DATE AND TIME	ON/OFF
		BALANCE ID	ON/OFF
		METHOD ID	ON/OFF
		COUNTER	ON/OFF
		DRYER SETUP	ON/OFF
		PRINTRATE	ON/OFF
		OPERATOR ID	ON/OFF
		CAL.-INFO	ON/OFF
		PRINT RATE	1.0 MIN
		OPERATOR	ttt...
SET HEADER	TITLE 1	ON/OFF	
	TITLE 2	ON/OFF	
	TITLE 1	ttt...	
	TITLE 2	ttt...	
MODE	PRINTER PC		

• SET APP. MENU		
	EDIT METHOD	ON/OFF
	METHOD ID	ON/OFF
	WEIGHING	ON/OFF
	UNIT	ON/OFF
	PRINT RATE	ON/OFF
	STANDBY TEMP.	ON/OFF
	AUTOSTART	ON/OFF

• SET ASH RESIDUE		
	<i>PBM 66 only</i>	
MODE	MANUAL/AUTO	
MEMORY CHOICE	ON/OFF	

■ 19 Menu trees

• **SET
BALANCE CAL.**

	MODE	OFF
		EXTERNAL
		EXT.-DEF.
		INTERNAL
		AUTO
DEF.		0.0000
		g

• **TEMP. AD-
JUSTMENT**

TEMP. AD- ON/OFF
JUSTMENT.

• **STABILITY**

STABILITY MEDIUM
HIGH

• **QUICK-START**

QUICK-START ON/OFF

• **SET
RS 232**

	BAUD RATE	300
		600
		1200
		2400
		4800
		9600
		19200
	PARITY	7-EVEN-1STOP
		7-ODD-1STOP
		7-NO-2STOP
	8-NO-1STOP	
	8-EVEN-1STOP	
	8-ODD-1STOP	
HANDSHAKE	NO	
	XON-XOFF	
	HARDWARE	
HID		ON/OFF

19 Menu trees

• SET USB DE- VICE

	MODECOM	PORT HID PORT	
	BAUD RATE	300 600 1200 2400 4800 9600 19200 38400 57600	<i>In mode COM-PORT</i>
	PARITY	7-EVEN-1STOP 7-ODD-1STOP 7-NO-2STOP 8-NO-1STOP 8-EVEN-1STOP 8-ODD-1STOP	<i>In mode COM-PORT</i>
	HANDSHAKE	NO XON-XOFF	<i>In mode COM-PORT</i>
	KEYBOARD LANGUAG.	NARROW SPEAR FRA TUR SPA	<i>In mode HID-PORT</i>
	FORMAT	LINES TABLES	<i>In mode HID-PORT</i>
	COLUMN FOR o	ON/OFF	<i>In mode HID-PORT</i>
	COLUMN FOR <>	ON/OFF	<i>In mode HID-PORT</i>
	UNIT	ON/OFF	<i>In mode HID-PORT</i>

■ 19 Menu trees

• SET USB HOST		
	MODE	KEY-BOARD SCAN- NER FOOT SWITCH FLASH DRIVE
	KEYBOARD LANGUAG.	ENG GER FRA TUR SPA
	SCANNER LANGUAGE	ENG GER FRA TUR SPA
	DEVICE TYPE	SINGLE DOUBLE
	FUNCTION	PRINT TARE OFF <i>In mode KEYBOARD</i>
	FUNCTION L.	PRINT TARE OFF <i>In mode SCANNER</i>
	FUNCTION R.	PRINT TARE OFF <i>In mode FOOT SWITCH DOUBLE type</i>
	GUARD	ON/OFF <i>In mode FLASH DRIVE</i>

• SET DATE AND TIME		
	DATE	[DD.MM.YY]
	DATE	[DD.MM.YY]
	TIME	[HH.MM.SS]
	FORMAT	STANDARD/US

■ 19 Menu trees

• PASSWORD	
PASS-WORD-----	PRIVACY OFF MEDIUM HIGH
	PASSWORD NEW - - - -

• THEFT CODE	
THEFT CODE ----	THEFT ON OFF
	CODE NEW - - - -

• KEYNOTE	
KEYSTROKE ----	KEYNOTE ON 1-9 OFF

• NOTE SOUND	
ALERT TONE ----	KEYNOTE ON 1-9 OFF

• BACKLIGHT	
LIGHTING ----	LIGHTING 1-9

• LANGUAGE	
	LANGUAGE ENGLISH
	LANGUAGE GERMAN
	LANGUE FRANCAISE
	DIL TURKEY
	IDIOMA ESPANOL

• SET JAM	
	FACTORY CONFIG. LOADING APPLICATION CONFIG. SHOP APPLICATION-CON- FIG.SPOKE

■ 19 Menu trees

10.2.2 Application Menu Tree

Press the "**MENU**" button while operating:

• LOAD METHOD	
LOAD METHOD	ttt... ttt... ttt... ttt... ttt...
• SAVE METHOD	
SAVE METHOD	
• DELETE METHOD	
DELETE METHOD	ttt... ttt... ttt... ttt... ttt...

■ 19 Menu trees

• METHOD	
METHOD	ttt...

• SETTING WEIGHT	
	TEST WEIGHT ON/OFF
	NOMINAL 5,000 g
	MAXIMUM 6,000 g
	MINIMUM 4,000 g

• UNIT	
UNIT	100-0%
	0-100%
	ATRO 100-999%
	ATRO 0-999%
	G/KG
	RESIDUAL WEIGHT
	WEIGHT LOSS

• PRINT RATE	
PRINT RATE	1.0 MIN

• STANDBY TEMP.	
STANDBY TEMP.	ON/OFF
TEMPERATURE	40 °C

• STARTUP	
STARTUP	ON/OFF

• AUTO OPENING	
AUTO OPENING	ON/OFF
TEMPERATURE	160 °C

■ 19 Menu trees

10.2.3 Button Menus

Press and hold the corresponding button until the desired menu item is displayed in the info line. The menu items "PRINT" and "TARA" are not displayed.

	• Start/stop button	
	START/STOP DRYING	<i>Not displayed</i>
	STATISTICS INFO	<i>Not for PBM 66</i>
	STATISTICAL RESET	<i>Not for PBM 66</i>
	ASH RESIDUE	

19 Menu trees

	• Print button	
	PRINT	
	RESET COUNTER	
	PRINT STATISTICS	
	PRINT STATUS	
	PRINT APPLICATIONS	
	PRINT CALF INFO	
	PRINT FIRMWARE HIST	

	• Tare button	
	TARE	
	HR MODE	ON/OFF
	BALANCE CALIBRATION	
	TEMP. CALIBRATION	

	• Change button	
	100-0%	
	0-100%	
	ATRO 100-999%	
	ATRO 0-999%	
	G/KG	
	RESIDUAL WEIGHT WEIGHT LOSS	

	• HEATING PROGRAM	
	BOOST TIME	3.0 MIN
	HEATING MODE	STANDARD
		BOOST SMOOTH

	• DRYING TEMPERATURE	
	TEMPERATURE	105 °C

	• DRYING	
	STOP TIME	10.0 MIN
	TIME STOP	ON/OFF

■ 19 Menu trees

	• STOPMODE	
	DIGIT/TIME	2/20
	%/TIME	0.2/20
	AUTO STOP	OFF DIGIT/TIME %/TIME ADAPTSTOP

PBM 60, PBM 60-HR

	• STOPMODE	
	AUTO STOP	1/20 D/S
	AUTO STOP	OFF 2/10 2/20 2/30 2/60 10/60 ADAPTSTOP DEF.

PBM 66